



NAME: Entrance (LCS-171) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *Mont. MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: SE Side

LOCATION OF NEGATIVES: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 1



NAME: Ranger Cabin--Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: Lance Olivieri

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 2



NAME: Entrance (LCS-171) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *MPA MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: South side

LOCATION OF NEGATIVES: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 3



NAME: Entrance (LCS-171) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *MDA, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: West side

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 4



NAME: Barn (LCS-473) Sherburne Ranger Station

Historic District

LOCATION: Glacier National Park *MRA, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/23/83

VIEW: SE side

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 1



NAME: Barn (LCS-473) Sherburne Ranger Station
Historic District

LOCATION: Glacier National Park *MRA, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: NE

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO#: 2



NAME: Barn (LCS-473) Sherburne Ranger Station
Historic District

LOCATION: Glacier National Park *MT, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: West

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 3



NAME: Barn--Sherburne Ranger Station

Historic District

LOCATION: Glacier National Park, MT *WNA*

PHOTOGRAPHER: Lance Olivieri

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 4



NAME: Garage (LCS-474) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: SE corner

LOCATION OF NEGATIVES: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 3



NAME: Employee Garage (474)--Sherburne

Ranger Station Historic District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: Lance Olivieri

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain

Regional Office, National Park Service,

Denver, CO

PHOTO NUMBER: 3



NAME: Entrance Checking Station--

Sherburne Ranger Station Historic District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: Lance Olivieri *RA*

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain

Regional Office, National Park

Service, Denver, CO

PHOTO NUMBER: 1



NAME: Entrance (LCS-476) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *MTA, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: NW

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, Co

PHOTO #: 1



NAME: Entrance (LCS-476) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *NEA, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: SW corner

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office National Park Service, Denver, CO

PHOTO #: 2



MANY GLACIER ENTRANCE

GLACIER HOUSE
1907-1908
W. H. HARRIS
J. H. HARRIS
J. H. HARRIS
J. H. HARRIS

NAME: Entrance (LCS-476) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *Mt. MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: NE

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office National Park Service, Denver, CO

PHOTO #: 4



NAME: Outhouse (LCS-601) Sherburne Ranger
Station Historic District

LOCATION: Glacier National Park *USA, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: SW

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 1



NAME: Out-house Sherburne Ranger Station
Historic District (LCS-651)

LOCATION: Glacier National Park *MRP, MT*

PHOTOGRAPHER: Glacier National Park

DATE: 9/25/83

VIEW: SW

LOCATION OF NEGATIVE: Rocky Mountain Regional
Office, National Park Service, Denver, CO

PHOTO #: 1



Emp. Residence HS - 171

Int. Center room

N wall

Sherburne RS#D

Glacier Co, MT, Glacier NP

Photo #1



Emp. Residence HS-171

Interior Kitchen

E wall

Sherburne RS HD

Glacier Co, MT, Glacier NP

Photo #2



Emp. Residence HS-171

Interior - SW bedroom

E wall

Sherburne RSHD

Glacier Co, MT, Glacier NP

Photo # 3



Emp. Residence HS-171

Interior - NW bedroom

E wall door

Sherburne RSHD

Glacier Co, MT, Glacier NP

Photo #4



Ness Hall HS-173

Interior Kitchen

facing N

Sherburne RSHD

Glacier Co, MT, Glacier NP

Photo #5



Mass Hall HS-173

Interior Kitchen

Facing W

Sherburne RSHD

Glacier Co, MT, Glacier NP

Photo #6



Barn HS-473

Interior

Facing W

Sherburne RSHD

Glacier Co. MT GLAC.

Photo # 7



Barn HS-473

Interior

Facing N

Sheekune RSHD

Glacier Co, MT GLAC

Photo 8



Woodshed HS-474

Interior - South

NW corner

Sherburne RS HD

Glacier Co, MT GLAC

Photo 9



Wood shed HS - 474

Interior N

S wall

Sherburne RS HD

Glacier Co, MT GLAC

Photo 10



Wood shed HS - 474

interior N

NW corner

Sherburne RSAD
Glacier Co, MT GLAC

Photo # 11



Checking Station - HS 476
Interior

Sheridan RSHD.

Glaciers MT 6LAL

Photo 12



Checking Station HS 4760
Interior

Shrub area RSHD

Glacier Co, MT 6LAC

Photo 13



Checking Station HS 4760
Intersect

Sherburne RS HD.

Glass Co. MT GLAC

Photo 14